


96. B Floor - Purchasing B7/B5 - View of acoustical plaster in storage room



97. B Floor - Purchasing B7/B5 - Location of dust sample #4 - top of storage shelf next to boxes

Case 01-01139-AMC Doc 13492-6 Filed 10/25/06 Page 3 of 3

## Hospital Administration Building Arkansas State Hospital (ASH)